


ELEVATION

APPOX. 2" CLEARANCE  
BEHIND SCULPTURE

STANDPIPE



PLAN

MOUNTINGS (5)

MOSAIC TILES  
IN POOL

GILDING FAILED 100%  
ON SCULPTURE

DEFORMATION

OPEN JOINT

EROSION & LOSS

CRACK

BLACK STAINING & CRUST

YELLOW STAINS & SCALE

BIOLOGICAL GROWTH  
THROUGHOUT  
BASIN, STAND & COPING

<p>CONSERVATION SOLUTIONS inc ART • ARCHITECTURE • ARTIFACTS</p>	
<p>FRENCH GILDED FOUNTAIN ASSESSMENT</p>	
<p>HILLWOOD MUSEUM &amp; GARDENS</p>	
<p>DATE: 5/10/17 DRAWN BY: mjr</p>	
<p><span style="color: magenta;">■</span> MARBLE</p>	
<p><span style="color: gold;">■</span> GILDED LEAD</p>	
<p><span style="color: red;">■</span> BRICK</p>	
<p><span style="color: blue;">■</span> TILE</p>	